

SAPC 24448

COPY 1 OF 1

10 February 1958

Dear Dan:

In a conversation on 6 February, I discussed with George K. the advisability of adding slack loops or elevators to the two negative machines. We find that the absence of these elevators leads to damage of the original films in the form of scratches, static marks and wrinkled edges. To date, this damage has been small but there is a potential for really serious loss of critical material. We estimate that these will cost approximately each for two.

In accordance with a verbal approval received from George we are proceeding to add these devices and will charge the work to PO-660.

ELG/njm
cc: J.L.B.
W.C.N.

ELG
E. L. G.

Low R approved Lchi

DOCUMENT NO. *340*
NO CHANGE IN CLASS. ☐
☐ DECLASSIFIED
CLASS. CHANGED TO: TS *S* C
NEXT REVIEW DATE: *2011*
AUTH: HR 70-2
DATE: *08/26/11* REVIEWER: 010956

PO 660